



# INSTRUCTIONS TOWER WIND COLLAR

## FOR BORDER BS-001 TYPE: VIIC U-552 / U-96 / U-82 1/35



The upper collar has a very bad and unrealistic shape.  
 We recommend using our 3D print repair kit.  
 Collar we have the exact shape for individual submarines U-552 / U-96 /  
 U-82. For the U-82 you must also use the SP-82 side panel item.

SKU-SP-82



SKU-L-96




this plastic must be removed




SKU-L-82




SKU-L-552



U-96



U-552



U-82

