

SKU-0205

# Products with 3D printing



version:  
black / gray



## TIP SHAPING BRASS SHEET

For a better shaping of etching, it is necessary to heat up plate and then rapidly cool down. Etching is soft and well shaped according to the shape of the hull. Recommendation: Try these steps to shape a different part of the sheet (the rest).

shaping

heating

cooling

gluing




We recommend using a filler (DodyFill 360) that covers the print lines on the product. You can then sand the surface with sandpaper for a smooth surface. If the product is designed for a functional model in water, all surfaces of the product must be colored by the filler.

## example

original surface

surface after use of the filler  
BodyFill360



**Do not expose to direct sunlight.**

The printing material is PLA. This is the same material as the RC models of aircraft. yet it is not recommended to leave it in the sun.

